
Powder Coating Study for starter motor




Air Point where sample is taken After MAEDA Filter

Air Point where sample is taken Before MAEDA Filter and After LTVS existing filter


Painting failure:
Before 40%
After 3%

Powder Coating Study for starter motor

Before MAEDA Filter



After MAEDA Filter



Before MAEDA Filter the Particles size from 0.3micron to 3.0micron was available in No: of counts as per enclosed picture

After MAEDA Filter the Particles size from 0.3micron to 3.0micron was '0' in No: of counts as per enclosed picture